

| | | | | | | | |
|--------|--|--|--|--|--|--|--|
| U.S.N. | | | | | | | |
|--------|--|--|--|--|--|--|--|

B.M.S. College of Engineering, Bengaluru-560019

Autonomous Institute Affiliated to VTU

January / February 2025 Semester End Main Examinations

Programme: B.E.

Semester : III

Branch: Mechanical Engineering

Duration: 3 hrs.

Course Code: 19ME3DCMSM

Max Marks: 100

Course: Materials Science and Metallurgy

Instructions: 1. Answer any FIVE full questions, choosing one full question from each unit.
2. Missing data, if any, may be suitably assumed.

| | | | UNIT - I | CO | PO | Marks |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---|----|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|-----------|--------------|
| Important Note: Completing your answers, compulsorily draw diagonal cross lines on the remaining blank pages. Revealing of identification, appeal to evaluator will be treated as malpractice. | 1 | a) | With a neat sketch of stress-strain diagram explain the following, Young's modulus, modulus of rigidity, Poisson's ratio, An elasticity and Yield strength. | CO1 | PO1 | 10 |
| | | b) | With neat sketches explain Fick's laws of diffusion. | CO1 | PO1 | 10 |
| OR | | | | | | |
| | 2 | a) | Explain ductile and brittle fracture with relevant sketches | CO1 | PO1 | 10 |
| | | b) | With neat diagrams explain a creep and fatigue curve. | CO1 | PO1 | 10 |
| | | | UNIT - II | | | |
| | 3 | a) | Draw a neat eutectic phase diagram and explain the same. | CO2 | PO1 | 10 |
| | | b) | Two metals A and B have their melting points at 900°C and 800°C respectively. The alloy pair forms a eutectic at 600°C of composition 60% B. They have unlimited liquid solubilities. The solid solubility of A in B is 10% and that of B in A is 5% at eutectic temperature and reduces to 0% at room temperature. Draw and label all fields. Find (i) the liquid and solid phase percentages of 20% B alloy at 650°C. ii) What is the composition of 20% B alloy at 50°C. | CO2 | PO1 | 10 |
| OR | | | | | | |
| | 4 | a) | Explain Hume Rothery rules for the formation of solid solutions with example. | CO2 | PO1 | 10 |
| | | b) | With the help of a neat sketch, explain an isomorphous phase diagram | CO2 | PO1 | 10 |

| UNIT - III | | | | | |
|-------------------|----|--------------------------------------------------------------------------------------------------------------------------|-----|-----|-----------|
| 5 | a) | With the help of a neat sketch, explain iron-iron carbide phase diagram and the invariant reactions in it. | CO2 | PO1 | 10 |
| | b) | Explain with a neat figure, the continuous cooling curves on TTT diagram | CO3 | PO1 | 10 |
| OR | | | | | |
| 6 | a) | With neat sketch, explain the procedure for construction of TTT diagram | CO3 | PO1 | 10 |
| | b) | List the alloying elements used in steels and state their effects on steel. | CO2 | PO1 | 10 |
| UNIT - IV | | | | | |
| 7 | a) | Explain in detail the annealing, normalizing, and hardening heat treatment processes. | CO4 | PO1 | 10 |
| | b) | Explain the types of cast irons. | CO4 | PO1 | 10 |
| OR | | | | | |
| 8 | a) | Explain in brief properties of polymers and ceramics. | CO4 | PO1 | 10 |
| | b) | Explain heat treatment process for non ferrous materials. | CO4 | PO1 | 10 |
| UNIT - V | | | | | |
| 9 | a) | Define composite materials. Give their classification and state the advantages and disadvantages of composite materials. | CO1 | PO1 | 10 |
| | b) | Explain with sketch pultrusion and filament winding process for composites manufacturing. | CO1 | PO1 | 10 |
| OR | | | | | |
| 10 | a) | Explain with neat sketch powder metallurgy and stir casting process | CO1 | PO1 | 10 |
| | b) | Explain with sketch hand lay up and vacuum bag molding processes for composites manufacturing. | CO1 | PO1 | 10 |
